

Please use an empty USB stick. Unzip the software package and copy the update file onto the USB drive.

Cable CAM (7p) – LBUS is required for updating software on cPRO motor and cPRO camin. (Can be used for power supply or update).

The cPRO_SW_PK_v5.0.2 applies to:

- cPRO hand unit
- cPRO PLUS hand unit
- cPRO ONE hand unit

Note: The RF communication protocol has been changed from version 5.0 and higher.

Therefore, wireless cPRO devices using version 5.0.2 will NOT be compatible with wireless cPRO devices running version 4.0.2 or lower.

Note: All cforce MINI motors in the daisy chain need to run SUP 1.3.4 or higher. All cforce PLUS motors in the daisy chain need to run SUP 1.3.0 or higher.

Note: The latest release version for the cPRO motor / cPRO camin is 5.0.1.

cPRO / cPRO PLUS / cPRO ONE hand unit:

Changes between 5.0.1 and 5.0.2

- bugfixes:
 - hand unit reset issue fixed:
 - when mounting / unmounting a camera interface or LCUBE CUB-1
 - when creating / editing an imperial lens file using a single focus value
 - simultaneous FRAM data management optimized
- others:
 - scale visualization improved for lens files with 2 scale values

cPRO PLUS hand unit:

Changes between 5.0.1 and 5.0.2

- bugfixes:
 - hand unit reset issue fixed:
 - advanced focus knob communication improved

cPRO motor / cPRO camin:

- known issues:
 - if connected to LCUBE CUB-1 (SUP 2.0.2), mounting / unmounting a camera interface causes the cPRO motor/camin to reset - does not affect operation